Ordinance March 16, 2024

- 2208 W 12th St
- 3100 W 16th St
- 1404 Pine St
- 1917 Valmar St
- 2801 Rock St


Ordinance March 16, 2024



2208 W 12th St

- Owner has failed to bring the structure into compliance.
- Date structure declared unsafe: September 2013
- HDP Remodel Estimate: \$ 51,485.01
- \$971.89 in Outstanding Liens.

*HDP – Housing Developer Pro





Front View



Side View






Roof View





Back View





Ordinance March 16, 2024



3000 W 16th St


- Owner has failed to bring the structure into compliance.
- Date structure declared unsafe: January 2015
- HDP Remodel Estimate: \$46,101.99
- \$1388.97 in outstanding Liens.

*HDP – Housing Developer Pro





Front View



Side View



Side View



3001 W 16th St. Ward 2

Roof View



3001 W 16th St. Ward 2

Back View



Ordinance March 16, 2024



1404 Pine St

- Owner has failed to bring the structure into compliance.
- Date structure declared unsafe: September 2016
- HDP Remodel Estimate: \$62,226.56
- \$609.16 in Outstanding Liens.

*HDP – Housing Developer Pro





Front View



Side View





Roof View



Back View



Ordinance March 16, 2024



1917 Valmar St

- Owner has failed to bring the structure into compliance.
- Date structure declared unsafe: January 2023
- Inspector Evaluation: \$60,069.70
- \$332.63 in Outstanding Liens.





Front View




Front View



Side View






Roof View





Back View



Ordinance March 16, 2024



2801 Rock St.

- Owner has failed to bring the structure into compliance.
- Date structure declared unsafe: February 2023
- Inspector Evaluation: \$76,167.41
- **\$0** in Outstanding Liens.






Front View



Side View





Roof View



Back View

